

- FREE CHLORINE
- **BROMINE**

Test Strips

- TOTAL CHLORINE
- ALKALINITY
- pH
- TOTAL HARDNESS
- CYANURIC ACID







Code 3028

Immerse strip for 2 SECONDS. Remove with pads face up. SHAKE ONCE TO REMOVE EXCESS WATER. Read immediately: FCI>TCI>Alk>pH>TH>CvA



(0)

(Br)

Alk

Alkalinity





3 5 10 (10)(6)(20)

 Keep wet fingers out of the hottle Close cap tiahtly after

> removing strip. In pools.

immerse strip to a depth

For best results

read in natural

Store in a cool.

daylight.

of 6".

- TCI Total Chlorine n 0.5 ppm
 - 10
 - In spas, turn off iets and immerse strip to a depth of 6"
- ppm 180 240 0 40 80 120 pН
 - 7.8 8.4

Purple color indicates excessive sanitizer

TH Total Hardness

ppm









150 250 0 40 100 For best results, pH must be between 7.0-8.4

LaMotte Company, Chestertown, MD 21620 USA www.lamotte.com/insta

dry place.



Drop holding box and dotted tolerance line