



INTELLIBRITE® 5G COLOR LED LIGHTS

2ND GENERATION AFTER 2009 REPLACEMENT PARTS



IntelliBrite 5g
Color LED Pool
Light



IntelliBrite 5g
Color LED Spa
Light

CALIFORNIA PROPOSITION 65 WARNING

⚠ **WARNING:** Cancer and Reproductive Harm.
 ⚠ **AVERTISSEMENT:** Peut Causer le Cancer
 et des Dommages au Système Reproducteur.
 ⚠ **ADVERTENCIA:** Cáncer y Daño Reproductivo.
www.p65warnings.ca.gov PH 200274A

Item	Part No.	Description
INTELLIBRITE 5g COLOR LED POOL LIGHT		
	620276	Replacement fuse for 12V only lights
1	79104800Z	Pilot screw with captive gum washer, brass
1	619355Z	Pilot screw with captive gum washer, SS
2	79110600	Face ring assembly, SS
3	79111000	Uni-tension wire clamp assembly
4	619864Z	Lens and gasket assembly, tempered
5	620400Z	Gasket, 8-3/8 in. diameter, silicone
6	620141	Nut, retaining
7	619818Z	Light engine kit, color 2nd generation
	600107	IntelliBrite 5g Demo with IntelliBrite Controller with hangers
	600108	IntelliBrite 5g Demo with IntelliBrite Controller without hangers
INTELLIBRITE 5g COLOR LED SPA LIGHTS		
1	79104800Z	Pilot Screw, with captive gum washer, brass
1	619355Z	Pilot screw with captive gum washer, SS
2	79111600	Face ring assembly, SS
3	79210400	Uni-tension wire clamp assembly w/ welded nut
4	640046	Lens and gasket assembly, tempered
5	79108600	Gasket, white, silicone

Note: IntelliBrite Spa light has no user serviceable parts inside.