


INTELLIPROXF® VSF PUMP

INTELLIPROXF VS PUMP - AFTER AUGUST 2015

REPLACEMENT PARTS



Item	Part No.	Description
INTELLIPRO XF PUMP		
1	352032Z	Drive Kit (VSF model)
1	356893Z	Drive Kit (VS model)
2	401655Z	Power End Kit (VS model)
3	355685	Drive Hardware Kit
4	401000	Wet End Assembly
5	410020	Union Kit w/o Tap
6	358527Z	Keypad Assembly Kit
7	356898Z	Drive (VSF model)
7	356892Z	Drive (VS model)
8	350306S	Motor
9	357160	Motor Support Insert
10	401004Z	Motor Base
11	071413	Acorn Nut (Qty. 10)
12	U43-12SS	Lock Washer (Qty. 10)
13	072184	Flat Washer (Qty. 6)
14	401002	Seal Plate
15	17351-0101S	Mechanical Seal
16	351446	Seal Plate O-Ring
17	400015	Impeller
18	37337-6080	Impeller Screw Set
19	400010	Diffuser
20	353323	Diffuser Screws

Item	Part No.	Description
21	350336	Diffuser O-Ring
22	401006	Lid/Locking Ring Assembly
23	400007Z	Strainer Basket
24	35505-1440	Lid/Locking Ring O-Ring
25	410001	2.5" C-Clip Locking Ring (Qty. 2)
26	411000	2.5" Union Nut (Qty. 2)
27	410002	2.5" Union Adapter w/o Tap (Qty. 2)
28	410016Z	2.5" Diamond Seal Kit (Qty. 2)
29	192115Z	Drain Plug O-Ring (Qty. 2)
30	357161Z	Drain Plug (Qty. 2)
NOT SHOWN		
	356905Z	Keypad Relocation Kit
	400032Z	Seal Plate w/Mech Seal
	350122	50 Ft. Communication Cable
	352501	Motor Fan Kit

CALIFORNIA PROPOSITION 65 WARNING


⚠ **WARNING:** Cancer and Reproductive Harm.
 ⚠ **AVERTISSEMENT:** Peut Causer le Cancer et des Dommages au Système Reproducteur.
 ⚠ **ADVERTENCIA:** Cáncer y Daño Reproductivo.

www.p65warnings.ca.gov

PA2012.1A

INTELLIPROXF® VARIABLE SPEED PUMP - BEFORE AUGUST 2015

REPLACEMENT PARTS



Item	Part No.	Description
INTELLIPRO XF PUMP		
1	401000	Wet End Assembly
2	410020	Union Kit Without Tap
3	401605Z	Power End Assy w/ Drive & Motor
4	401006	Lid/Locking Ring Assy
5	400007Z	XF Series Replacement Basket
6	35505-1440	Lid/Locking Ring O-Ring
7	357161Z	Drain Plug (2 req.)
8	192115Z	Drain Plug O-ring (2 req.)
9	411000	2.5 in. Union Nut
10	410001	2.5 in. C-Clip Locking Ring
11	410002	2.5 in. Union Adapter
12	410016Z	2.5 in. Diamond Seal Kit - (Includes two)
13	401004Z	Motor Base
14	357160	Motor Support Insert- Black
15	071413	Acorn Nut (each)
16	U43-12SS	Split Lock Washer (each)
17	072184	Flat Washer (each)
18	350336	Diffuser O-ring
19	353323	Diffuser Screw
20	400010	Diffuser
21	37337-6080	Impeller Reverse Screw

Item	Part No.	Description
22	351446	Seal Plate O-Ring
23	400015	Impeller Assembly
24	17351-0101S	Mechanical Seal Assembly
25	401002	Seal Plate
26	357294S	Motor Kit
27	350612	Drive Hardware and Gasket Kit (Incl. item # 31)
28	353252	Variable Speed Drive Assy Kit
29	353310	Field Wiring Comp Kit w/ Gasket
30	350701	Control Cover Assy Kit (incl. item #27) ¹
30	401100	Control Cover Assy Kit (incl. item #27) ²
31	350107	Screw 10-24 x 3-1/4 in. PH MS 18-8SS (Qty. 3)
32	352501	Motor Fan Kit (contains Fan, Shroud, Hardware)
NOT SHOWN		
	400032Z	Seal Plate Kit w/ Mech Seal
	400012	Riser Plate XF to Challenger
	350122	50 Ft. Communication Cable

CALIFORNIA PROPOSITION 65 WARNING

⚠ WARNING: Cancer and Reproductive Harm.
⚠ AVERTISSEMENT: Peut Causer le Cancer et des Dommages au Système Reproducteur.
⚠ ADVERTENCIA: Cáncer y Daño Reproductivo.
www.p65warnings.ca.gov

¹ Used on pumps manufactured before 7/2/13

² Used on pumps manufactured after 7/2/13 to present